ECS Configuration	n Change .	est		P	age 1 of 🔑	Pages
CCR No. 98-0	148 Logged [Date 2/6/98	Rev	Request Ty	pe CCR	
Priority Routine [X Urgent	Emergency	Affected Release		Change Class	II
Title (description) Upgrade of HiPPI Switch controller card						
Documents Affected These SW N/A baseline.	in in	he current	Source Nos (RID, I Tech Reference N/A	NCR, Action Ite	em, GSFC CCR, e	etc.) or
RTM Change	Start New Bas	eline	1			
Problem: The ECS project currently has five High Performance Parallel Interface (HiPPI) switches deployed as part of Rel B. These HiPPI switches contain varying levels of Switch Control Card (SCC) firmware versions which need to be upgraded to one consistent version level.						
Proposed Solution Upgrade the switches to a baseline line level of version 2.05 for the Switch Control Card Ethernet Management Module (SCC EEMM) and version 2.23 for the SCC firmware. The first installation will be done in the MiniDaac, then LaRC and EDC. The installation for the MiniDaac can be done within the next week, LaRC and EDC will have to be coordinated with DAAC site M&O liaisons. (Baselined in CCE 48-0152)						
,						
Impact Analysis: Organizations Affected:	800 □	Contracts	ECS Chief Eng	FOS [M&O	
Procurement	∞ □	Rel. Dev	Rei. A	Rel. C	SCDO Arch.	
Science Off	Security	Subcontret	Sys. Eng	Sys Verf Acpt		
Cost:	None 🗓	Small 🔲	Medium	Large 🔲		
		(Not exceeding \$100,000)	(\$100,000 to \$500,000)	(Over \$500,000)		
Schedule:	None x	Other				
Additional LOC			Man-Month	ns		
Materials						
Originator Ron Parham	1	Tenald	Joshan-		2/4/98 Date)
Office H/W Engr.	_ Office Manager	Rad Signature	1. Milla		2/6/98 Date	,
Disposition	Approved	Approved w/Com	ment Forv	vard	Disapproved	
Comments:						
	CCB Chairperson	Signature	Gent		2/9/98	Pate
CM01OC96			 			ECS
					m/1	

ORIGINAL

at/cm